

3/11




Fig 4




Fig 5

4/11




Fig 6

5/11




Fig 7

6/11




Fig 8

7/11

90

Maintenance Log for Test sensor

Log:

2003-04-16 11:02: Sensor installed by Henrik Larne

Time: Entry:

2003-04-16 11:02 Sensor installed by Henrik Larne

92

New Entry Save Log Close

**Fig 9**

8/11




Fig 10

9/11




Fig 11

10/11

120




Fig 12